

Executive Summary

This Tech Bulletin describes how to properly connect the USB-C Power Adapter to the Windows I-Series 2.0 Devices.

Steps

1. With I-Series 2.0 device lying face down on a protective work surface, use the #1 Philipps screwdriver to remove the security screw.



2. Pull the plastic cover up and off to access the USB-C power connection.



- a. Location of USB-C power connection.



- 3. Remove the USB-C Power Adapter from the accessory box.



4. Plug USB-C power adapter into the USB-C power port on back of the I-Series 2.0 device.



- a. Connector plugs in the upward direction.



5. Replace plastic cover and security screw.

