

## Executive Summary

This process document explains requirements for enabling the integrated webcam on an I-Series 3.0 device that has been upgraded to MR-1 image (4.36.60) from MR-0 image (4.26.140). This procedure is applicable only to devices that **did not** ship with MR-1 or above from the factory. For devices that shipped with device version 4.36.60, this step has been completed at the factory and is not required.

## Affected Elo Devices

I-Series 3.0 for Android™ with Google™ Play Services

## Required Components

I-Series 3.0 for Android™ with Google™ Play Services

USB A-to-A cable

Computer with fastboot installed (Windows/Mac/Linux)

## Affected EloView device versions

4.36.60 (only if upgraded from 4.26.140)

## Procedure

1. Connect USB A-to-A cable between I-Series and Fastboot-equipped computer
2. Enter Fastboot mode by holding HOME key, connecting power to I-Series and releasing button when Android Recovery menu is visible
3. Select “Reboot to bootloader” (*Fastboot mode* will appear on-screen)
4. Type “fastboot devices” – serial number will appear
5. Type “fastboot oem oemcamera Qon”

```
C:\>fastboot devices
A193920003      fastboot

C:\>fastboot oem oemcamera Qon
...
OKAY [ 0.017s]
finished. total time: 0.020s
```

6. Reboot device
7. Camera is now enabled

## Additional Details

As always, if you have any questions don't hesitate to reach out to EloView Support Team for further assistance.

We can be reached by calling (844) 435-6832 or by emailing [support@eloview.com](mailto:support@eloview.com).